





The MAB 1300 magnetic core drilling machine is currently the strongest magnetic core drilling machine available with a reversible motor. The appearance of these drills alone shows what they are about: Pure power! 2,300 W powerful motor, four-speed gear-box and a full package of features leave nothing to be desired. This magnetic core drilling machine meets all the requirements made by heavy-duty structure engineering, shipbuilding, and mechanical engineering. Core drilling capacity up to 130 mm diameter (30 mm cutting depth) is possible. The full range of the BDS core drills can thus be utilized to its full extent. As standard, the MAB 1300 has a direct arbor with a 32 mm Weldon shank. Without the solid steady, which can be removed very easily, the stroke of the drill increases to an impressive 310 mm. The MAB 1300 magnetic core drilling machine is also fully equipped with all the safety features of modern magnetic core drill technology. The premium feature of the MAB 1300 is the Power-Assist, servo-assisted drilling for effortless drilling, especially for larger diameters.

MAB 1300	
Motor output	2,300 W
Voltage	230 V AC, 50 - 60 Hz
Stroke/without steady	85/310 mm
Magnet dimensions	120 x 360 x 65 mm
Weight	51 kg
Spindle taper	MT 4
Gear 1 range: 30 – 80 rpm	Gear 2 range: 50 - 120 rpm
Gear 3 range: 130 - 350 rpm	Gear 4 range: 210 – 550 rpm
Safety clutch	✓
Permanent internal lubrication	✓
Torque control	✓
Full wave control electronics	✓
Magnet indicator	✓
Overheating protection	✓
Clockwise/anticlockwise rotation	✓
Carbon brush wear indicator	✓
Power-Assist servo drilling	✓
MAB 1300 230 V	
MAB 1300 110/125 V	



Includ	ed	in	deli	verv

- 1 Magnetic core drilling machine
- 1 Carry case on wheels
- 1 Safety lashing strap
- 1 Offset screwdriver size 4, 6, 8
- 1 Ejector pin ZAK 075, 090, 100, 120
- 1 Ejector drift MT 4
- 1 Bushing ZAP 200 from Weldon 32 mm to 19 mm
- 1 Operating instructions

Core drill	Twist drill	Reamer	Countersink	Tapping
Max. Ø 130 mm Cutting depth: 30-55-75-110 mm	Ø 45 mm	Ø 50 mm	Ø 80 mm	M42











Note:

When using core drills with a cutting depth of 110 mm, the steady must be removed. In addition, you require a MT 4 ZIA 419-KN or ZIA 432-KN industrial arbor.

